
LOPI FLUSH WOOD MEDIUM NEX-GEN SPARE PARTS - EFFECTIVE 1 SEPTEMBER 2024

Door Parts



| ID# | Description | Qty | Part # | \$ | Other Detail |
|---------|-------------------------------------|-----|-----------|-------|----------------------|
| 1 | Gasket Cement, 4 oz. | 1 | 250-04477 | | See your Lopi Dealer |
| 2 | Door Gasket, 3/8" x 80" | 1 | 99900429 | \$72 | |
| 3 and 4 | (4) Clips w Screws, Gaskets - Rect. | 1 | 250-02191 | \$44 | |
| 5 | Glass (w Gasket) - Rectangular | 1 | 250-02183 | \$320 | |
| 6 | Glass Gasket (1/4" X 76") | 1 | 250-02184 | \$15 | |
| 7 | Handle Assembly | 1 | 250-02196 | \$95 | |
| 8 | Wood Handle w Screw | 1 | 250-01305 | \$26 | |

Replacing the Glass




The glass must not contact the door retainer or glass clips directly. The glass gasket and glass clip gaskets insulate the glass to prevent cracking. Do not over-tighten the glass clips. Use only 5mm thick neo-ceramic glass.

Lay the glass gasket in the doorframe (cut off excess gasket). Place the glass on the gasket. Secure the glass clips to hold the glass in place (make sure the glass clip gaskets are in place).

Replacing the Door Gasket

The door gasket inbuilts into the outer groove of the door retainer. Stove gasket cement holds it in place. Before installing, remove any residual cement. Lay the gasket in place (start at the lower left corner) and cut off any excess gasket (do not stretch the gasket. The cement fully cures with heat from the stove. You may need to open and close the door repeatedly to get the gasket to seat fully.



| ID# | Description | Qty | Part # | \$ | Other Detail |
|-----|--------------------------------|-----|-----------|------------|--------------|
| 1 | Sec. Air Tubes w Pins (all 4) | 1 | 98900258 | \$166 | |
| 2 | Air Tube Pin (w Screw) | 4 | 250-02186 | \$15 | |
| 3 | Front Baffle Support | 1 | 250-05505 | TBA - Call | |
| 4 | Brick, Cut 9" x 2-1/2" x 3/16" | 2 | 251-00089 | \$27 | each |
| 5 | Brick, Cut 9" x 1-3/8" | 1 | 251-00018 | \$27 | each |
| 6 | Brick, Full 9" x 4" | 1 | 251-00000 | \$27 | each |
| 7 | Brick, Cut 4" x 5-1/2" | 1 | 251-00090 | \$27 | each |
| 8 | Rear Baffle Support | 1 | 250-05506 | TBA - Call | |
| 9 | Damper Slide Plate | 1 | 250-05504 | TBA - Call | |
| 10 | Damper Slider | 1 | 250-03596 | \$87 | |
| 11 | Yoke | 1 | 98900331 | \$53 | |
| 12 | Damper Extension Rod & Ring | 1 | 98900333 | \$68 | |